

NOTICE OF FIRE SAFETY INSPECTION

OREGON STATE UNIVERSITY



Facility Inspected:	Gilbert Addition
Date Inspected:	14-Sep-06
Reinspect Date:	26-Oct-06
Reinspect Time:	10:00 AM
EH&S Rep:	Pete

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection please phone me at 766-6903. Thank you for your cooperation and support for fire safety. *Jim Patton, Fire Prevention Officer, jim.patton@ci.corvallis.or.us*

NOTE	Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.
*	<i>Annotates a deficiency identified by OSU Environmental Health & Safety Department. Direct any questions regarding these items to that office (737-2273).</i>

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible groups and begin corrective action as soon as possible.

Facility Services Priority Codes:	
Priority 1 –	(p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be
Priority 2 –	(p2) items should be corrected within the five-week period before the
Priority 3 –	(p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Andrew Grey at extension 7-7651. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department contact the Customer Service Unit at ext. 7-2969. MS Excel format is available upon request.

Responsible Party	Area	Description	Code Reference
DEPT	Rm. 12	If dispensing of flammable liquids is to continue in 5 gallon containers or larger it shall be done within an approved exhaust hood and approved grounding and bonding shall be in place.	
FS-2	Fire Sprinkler System	Inspect and test in accordance with nationally recognized standards.	
EHS	Rm. 103	Remove fire extinguisher not mounted or required in this area.	
EHS	Rm. 209	Replace BC fire extinguisher with a 2A:10BC extinguisher	
DEPT	Rm. 318	Reduce quantity of flammable gas to one large cylinder or a maximum of two if both in use.	
FS-2	Nr. 408	Repair EXIT sign. Bulb out.	
FS-2	Roof	Install permanent sign over standpipe connection indicating: "CONTROL VALVE INSIDE" Sign shall be red on white or white on red.	
EHS	Fifth floor	Replace fire extinguisher. Low pressure.	