

**NOTICE OF FIRE SAFETY INSPECTION
OREGON STATE UNIVERSITY**



Facility Inspected: GILBERT HALL
 Date Inspected: 23-Sep-11
 Reinspect Date: 20-Oct-11
 Reinspect Time: 9:00 AM

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could

NOTE Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and
 * Annotates a deficiency identified by OSU Environmental Health & Safety Department. Direct any questions regarding

Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin

Facility Services Priority Codes:

- Priority 1 – (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.
- Priority 2 – (p2) items should be corrected within the five-week period before the scheduled re-inspection.
- Priority 3 – (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 7-3066. If assistance is required from Facilities Services to estimate or

Responsible Party	Area	Description	Code Reference
FS/P2	Fire Extinguishers	Extinguishers shall be tagged and inspected annually. Recharge every 6 years. Hydro-test every 12 years.	CFC 906.2, NFPA 10
DEPT/P2	Vacated Labs	Remove all hazard placards once Pete has collected material.	
FS/P2	Third floor East End	Remove fire extinguisher bracket. Fire extinguisher not required.	
DEPT/P2	All Labs	Provide and post a copy of the campus Emergency Procedures Guide (Contact the Public Safety Dept.) in appropriate commons areas and Lab Safety Reference Guide (Contact the EH&S Office) in every lab containing chemicals.	CFC 404 & 2701.3.3.15
FS/P2(PETE)	All Labs	Remove quantity of excess chemicals that have been left behind from the move out to the LPSC.	
DEPT/P2	Rm. 338	Label all chemical containers (1 gallon and larger) as to plain language contents & associated hazard. *All containers should be labeled	CFC 2703.5.1
DEPT/P2	Rm. 328A	Discontinue practice of storing breakable chemical containers on floor	CFC 2703.9.2

DEPT/P2	Rm. 328	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable. WHITE ZIP CORD UNDER DESK.	CFC 605.4, 605.5
FS/P2	Rm. 238	Restore or remove exposed outlet wiring on work table against interior wall.	CFC 605
DEPT/P2	Rm. 328	*Fume Hood #3 - Replace cover to vaccum pump fan belt mech. Danergous situation!	EH&S
DEPT/P2	Rm. 328	*Near Fume Hood #3 - Discard old desktop fan with large openings	EH&S
DEPT/P2	Rm. 328	Near Fume Hood #1 - Plug power strips directly into outlet. Do not chain one to another.	CFC 605.4.2
DEPT/P2	Rm. 255	Replace protective caps on all high pressure cylinders not actively in use	CFC 3003.4
FS/P2	Second floor	Fire doors / smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided. ADJUST TO CLOSE AND LATCH UNAIDED.	CFC 703.2
DEPT/P2	Rm. 255	Discontinue the use of non fuse protected extension cords in place of permanent wiring. Fuse protected power strips are acceptable.	CFC 605.4, 605.5
DEPT/P2	Rm. 255	Plug power strips directly into outlet. Do not chain one to another.	CFC 605.4.2
DEPT/P2	Rm. 255	Remove excess material from exit paths.	CFC 315.2.2, 1027
DEPT/P2	Rm. 255	Label all chemical containers (1 gallon and larger) as to plain language contents & associated hazard. *All containers should be labeled	CFC 2703.5.1
DEPT/P2	Rm. 235	Plug power strips directly into outlet. Do not chain one to another.	CFC 605.4.2
FS/P2	Near 223	Hallway - Label gas piping in hallway.	CFC 3003.2.3
DEPT/P2	Rm. 224	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES. <u>WOOD AND OTHER MATERIAL IN LOWER EXITWAY. PLEASE MAKE SURE THIS MATERIAL IS REMOVED PRIOR TO CLASSES STARTING.</u>	
FS/P2	Rm. 215	Door to Men's Rm. - Adjust door closer to close door tightly.	CFC 703.2
DEPT/P2	Rm. 213	Secure pressurized gas cylinders	CFC 3003.3.3
FS/P2	Rm. 115	Vaccum pump motor extremely hot and making unusual noise. Please investigate	

DEPT/P2	Rm. 124	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES. REMOVE BLUE CHAIRS FROM NEAR EXITWAY. PLACE IN ADA AREA ABOVE OR REMOVE FROM ROOM.	CFC 315.2.2, 1027
DEPT/P2	Rm. 154B	Restore static control bonding to all 55 gallon drums where flammable liquid is being dispensed	CFC 2703.9.5
DEPT/P2	Near Rm. 46	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES. DO NOT LEAVE ITEMS FOR SURPLUS IN HALLWAY FROM MORE THAN 8 HOURS.	CFC 315.2.2, 1027
DEPT/P2	Rm. 39	Fire doors / smoke barriers shall be maintained and kept free of obstructions. Doors shall close and latch unaided. DO NOT HOLD DOOR OPEN IN UNAPPROVED MANNER. PROVIDE AN APPROVED MAGNETIC DEVICE.	CFC 703.2
DEPT/P2	Flammable Storage Rm.	Restore static control bonding to all 55 gallon drums where flammable liquid is being dispensed	CFC 2703.9.5
DEPT/P2	Rm. 14	Remove inaccurate signage on door.	