

**NOTICE OF FIRE SAFETY INSPECTION  
OREGON STATE UNIVERSITY**



Facility Inspected: GILBERT HALL  
 Date Inspected: 23-Sep-11  
 Reinspect Date: 2-Nov-11  
 Reinspect Time: 9:00 AM

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection please phone me at 7-3066. Thank you for your cooperation and support for fire safety. *Jim Patton, Fire Prevention Officer, jim.patton@oregonstate.edu*

**NOTE** Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.

\* *Annotates a deficiency identified by OSU Environmental Health & Safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facility Services Priority Codes:

- Priority 1 – (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made
- Priority 2 – (p2) items should be corrected within the five-week period before the
- Priority 3 – (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Jim Patton (Corvallis Fire Department) at 7-3066. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department contact the Customer Service Unit at ext. 7-2969. MS Excel format is available upon request.

Responsible Party	Area	Description	Code Reference
DEPT/P2	Vacated Labs	Remove all hazard placards once Pete has collected material.	

Responsible Party	Area	Description	Code Reference
FS/P2	Third floor East End	Remove fire extinguisher bracket. Fire extinguisher not required.	
DEPT/P2	All Labs	Provide and post a copy of the campus Emergency Procedures Guide (Contact the Public Safety Dept.) in appropriate commons areas and Lab Safety Reference Guide (Contact the EH&S Office) in every lab containing chemicals.	CFC 404 & 2701.3.3.15
FS/P2(PETE)	All Labs	Remove quantity of excess chemicals that have been left behind from the move out to the LPSC.	
DEPT/P2	Rm. 328A	Discontinue practice of storing breakable chemical containers on floor	CFC 2703.9.2
FS/P1	Rm. 328	Restore or remove exposed outlet wiring on work table against interior wall.	CFC 605
DEPT/P1	Rm. 224	Remove storage and obstructions from exits, aisles, corridors, and stairs. EXITWAYS SHALL BE KEPT CLEAR AT ALL TIMES. <b><i>WOOD AND OTHER MATERIAL IN LOWER EXITWAY. PLEASE MAKE SURE THIS MATERIAL IS REMOVED PRIOR TO CLASSES STARTING.</i></b>	